



Photo 1 – Standing along Elk Road, on the northeast most corner of the site, looking west into the existing vegetation on the site.



Photo 2 – Standing along Elk Road, on the northeast most corner of the site, looking northwest along Elk Road.



Photo 3 – Standing along Elk Road looking southeast in the direction of the adjacent property situated on Elk Road.



Photo 4 – Standing along Elk Road looking southwest towards Buck Road at the closet vegetation to the northwest most part of the site.



Photo 5 – Standing along Elk Road at the midpoint of the street frontage looking due south at the existing vegetation.



Photo 6 – Standing on the northwest corner of the site looking north towards the intersection of Buck & Elk Road.



Photo 7 – Standing on the northwest corner of the site looking northwest towards the intersection of Buck and Elk Road.



Photo 8 – Standing on the northwest corner of the site looking south toward Buck Road.



Photo 9 – Standing on the northwest corner of the site, along buck road, looking west at the adjacent property.



Photo 10 – Standing on the northwest corner of the site looking south toward Buck Road.



Photo 11 – Standing along Buck Road, around the midpoint of the street frontage, looking south along Buck Road.



Photo 12 – Standing along Buck Road, further south of photo 11, looking south along Buck Road.



Photo 13 – Standing along Buck Road, further south of photo 12, looking north along Buck Road.



Photo 14 – Standing along Buck Road, looking east towards the existing vegetation within the site.



Photo 15 – Standing along Buck Road, across the street from the site, looking west at an existing pipe outfall.



Photo 16 – Standing along Buck Road, across the street of the site, standing uphill of the existing pipe outfall looking south.

